
## MARION COUNTY SURVEYOR'S OFFICE

DEBRA S. JENKINS MARION COUNTY SURVEYOR SECTION CORNER RECORD SEC. 11 TWN.  $16_{\rm N}$  RNG.  $3_{\rm E}$ 

BRYAN F. CATLIN, PLS TECHNICAL SUPERVISOR

THE POSITION BASED ON

RECORD CORNERS.



Original post set by Hosbrook 1-3-1855 with witnesses: 16" hackberry S 71 W 16.5 links distant, 8" ash S 40 E 11 links distant per Washington Township Legal Survey Book pg. 15. 52nd Street Bridge over the Water Co. Canal plans show a 3" pipe in '55 (Drawer 30 - Drawing 57). 10-4-95 Kiste excavated and recovered a 1/2" rebar 4" down, and a 4" diameter lead pipe 24" long 12" down, 4" lead pipe agreed with other monumentation per the plat of the Town of Rocky Ripple by H. Bloemker 8- '27 per Washington Township Legal Survey Book pg. 136 and was accepted as "the center" by MCSO. 10-5-95

16031105

16031105		
REF.	DISTANCE	DESCRIPTION
1.	20.74'	Cut 'x' S-rim of sewer manhole
2.	37.81'	1/2" rebar :MSE property corner : JOB#121-2213 1-11-94
3.	28.23'	PK nail SE PwP#256-335 B 6"up
4.	42.53'	NW corner of storm inlet
5.	98.33'	PK nail E PwP#235-365 A L 48"up
6.	30.51'	PK nail SW PwP#111-3342 6"up
		THIS CORNER POSITION
		THIS CORNER POSITION REPRESENTS A "TITLE" CORNER AND MAY NOT
		NECESSARILY REPRESENT